

Маркировка	DN	L	D	D1	D2	Φn	Z	F	C
Q41F-25C-200	20	130	105	28	55	14	4	2	16
Q41F-25C-250	25	140	115	34	65	14	4	2	16
Q41F-25C-320	32	165	135	42	78	18	4	2	18
Q41F-25C-400	40	165	145	48	85	18	4	3	18
Q41F-25C-500	50	203	160	57	100	18	4	3	20
Q41F-25C-650	65	222	180	76	120	18	8	3	22
Q41F-25C-800	80	241	195	89	135	18	8	3	22
Q41F-25C-100	100	305	230	108	160	23	8	3	24
Q41F-25C-125	125	356	270	133	188	25	8	3	28
Q41F-25C-150	150	394	300	159	218	25	8	3	30
Q341F-25C-200	200	457	360	219	278	25	12	3	34
Q341F-25C-250	250	533	426	274	332	30	12	3	36
Q341F-25C-300	300	610	485	324	390	30	16	4	40
Q341F-25C-350	350	686	550	377	448	34	16	4	44
Q347F-25C-400	400	762	610	426	505	34	16	4	48
Q347F-25C-500	500	914	730	530	610	41	20	4	52
Q347F-25C-600	600	1067	840	630	718	41	20	5	56
Q347F-25C-700	700	1346	955	720	815	48	24	5	60
Q347F-25C-800	800	1524	1070	820	930	48	24	5	64
Q347F-25C-900	900	1727	1180	920	1025	54	28	5	66
Q347F-25C-1000	1000	1900	1305	1020	1140	58	28	5	68

Q347F-25C-1200	1200	2100	1525	1220	1350	58	32	5	72
----------------	------	------	------	------	------	----	----	---	----